



M2632

Figure 1
Flight Profile

Takeoff: Engine Failure After V_1 with APR-High and Low Performance Profiles