


Balked Landing and Go-Around, Missed Approach Two Engines

Fly published missed approach
airspeed 180 kt or as directed

NOTE:
Selecting flight director go-around mode
disengages the autopilot and provides a
noseup pitch command and heading
at the time of selection



PF
PMF
• • CALL RESPONSE

Go-Around – Two Engines